

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BZ389
West
1/2-1
0.625 mi.
3298 ft.

SUFSIDE MARINA
W. 22ND & W. 23RD STS
BROOKLYN, NY

NY LTANKS **S101340986**
N/A

Site 5 of 5 in cluster BZ

Relative:
Higher

LTANKS:

Actual:
0 ft.

Name: SUFSIDE MARINA
Address: W. 22ND & W. 23RD STS
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9406145 / 1994-08-05
Facility ID: 9406145
Site ID: 68579
Spill Date: 1994-08-05
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: 1994-08-05
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1994-08-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: Federal Government
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-10-19
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: MOBIL HOME TRAILER
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 65301
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 10/10/95: This is additional information about material spilled from the translation of the old spill file: GARBAGE & RAW SEWAGE."

Remarks: "REFER TO SPDES"

All Materials:

Site ID: 68579
Operable Unit ID: 1000314
Operable Unit: 01
Material ID: 379197
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported